


POWER CONNECTION

AC SUPPLY

VOLT FREE CONTACT CONNECTION



(S) = SWITCH (to supply a continuous signal until end of travel is reached).

eg: THERMOSTAT
RELAY
FLOAT/LEVEL SWITCH
MANUAL SWITCH
ETC.

VOLT FREE CONTACTS:
Factory set at 0 & 90°
Switches rated 220V 5A

Above wiring showing same supply as motor is only a suggestion.

NB: READ INSTALLATION, OPERATION & MAINTENANCE INSTRUCTIONS BEFORE CONNECTING.

AC WIRING DIAGRAM FOR ALL STANDARD REVERSIBLE ACTUATORS.

J+J
ACTUATORS

Drawn By
MRG

Chk
DC

File Name
WRAC

Scale
NTS

Dwg No.

WRAC

Revision
1


Sheet
1/1

Date
14/06/00

POWER CONNECTION

DC SUPPLY

VOLT FREE CONTACT CONNECTION



(S) = REVERSING POLARITY SWITCH
(to supply continuous signal until end of travel is reached)

VOLT FREE CONTACTS
Factory set at 0 & 90°
Switches rated 220V 5A

Above wiring showing same supply as motor is a suggestion only.

NB: READ INSTALLATION, OPERATION & MAINTENANCE INSTRUCTIONS BEFORE CONNECTING.

DC WIRING DIAGRAM FOR ALL STANDARD REVERSIBLE ACTUATORS.

J+J ACTUATORS	Drawn By MRG	Chk DC	File Name WRDC	Scale NTS
	Dwg No. WRDC	Revision 1	Sheet 1/1	Date 14/06/00